

DART AEROSPACE LTD	Work Order :	22582
	Description:	Inspection
	Approval :	<i>RB</i>
		Page 1 of 1

Step	Location	Procedure	By	Date																												
1	PK	Remove from Stock Yes/No Return# <u>352</u> <table border="1"> <thead> <tr> <th>Qty</th> <th>Part Number</th> <th>Description</th> <th>Batch</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>D3145-1</td> <td>Bracket</td> <td>B21383A</td> </tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table>	Qty	Part Number	Description	Batch	1	D3145-1	Bracket	B21383A																					<i>RB</i>	05.03.01
Qty	Part Number	Description	Batch																													
1	D3145-1	Bracket	B21383A																													
2		Re-work/Inspection: (A) Reproduction as per QSI CCS (B) Inspect level 3	<i>MSG</i> <i>CL</i>	05/03/09 05/03/14																												
3	PK	Identify & Stock: <table border="1"> <thead> <tr> <th>Qty</th> <th>Part Number</th> <th>Description</th> <th>Batch</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>D3145-1</td> <td>Bracket</td> <td>B21383A</td> </tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table>	Qty	Part Number	Description	Batch	1	D3145-1	Bracket	B21383A																					<i>CL</i>	05/03/14
Qty	Part Number	Description	Batch																													
1	D3145-1	Bracket	B21383A																													
			<i>9.5J</i>	<i>SUC</i> 05.03.17																												
	PC	Close W/O Inspect Level 21	<i>MS</i>	05.03.18																												